

Calvert High School

2018-2019 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date Water Last Used	Time Water Last Used	Date Sample Collected	Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	1	DF	fountain outside cafeteria	FD	3/13/2019	8:00:00 PM	3/14/2019	4:51:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	2	DF	bottle filler outside cafeteria	FD	3/13/2019	8:00:00 PM	3/14/2019	4:51:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	3	DF	fountain outside 217	FD	3/13/2019	8:00:00 PM	3/14/2019	4:54:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	4	DF	left fountain outside 213	FD	3/13/2019	8:00:00 PM	3/14/2019	4:56:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	5	DF	right fountain outside 213	FD	3/13/2019	8:00:00 PM	3/14/2019	4:56:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	6	DF	left fountain outside nurse room	FD	3/13/2019	8:00:00 PM	3/14/2019	4:59:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	7	DF	middle fountain outside nurse room	FD	3/13/2019	8:00:00 PM	3/14/2019	4:59:00 AM	3/15/2019	<1.0	No

Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	8	DF	right fountain outside nurse room	FD	3/13/2019	8:00:00 PM	3/14/2019	4:59:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	9	DF	left fountain by 402	FD	3/13/2019	8:00:00 PM	3/14/2019	5:05:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	10	DF	middle fountain 402	FD	3/13/2019	8:00:00 PM	3/14/2019	5:05:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	11	DF	right fountain 402	FD	3/13/2019	8:00:00 PM	3/14/2019	5:05:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	12	DF	left fountain outside 109	FD	3/13/2019	8:00:00 PM	3/14/2019	5:08:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	13	DF	right fountain outside 109	FD	3/13/2019	8:00:00 PM	3/14/2019	5:08:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	14	DF	left fountain outside 111	FD	3/13/2019	8:00:00 PM	3/14/2019	5:10:00 AM	3/15/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	15	DF	right fountain outside 111	FD	3/13/2019	8:00:00 PM	3/14/2019	5:10:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	16	DF	left fountain outside 113	FD	3/13/2019	8:00:00 PM	3/14/2019	5:14:00 AM	3/18/2019	<1.0	No
Water Testing	Calvert High School	3/30/2019	1	17	DF	right fountain outside 113	FD	3/13/2019	8:00:00 PM	3/14/2019	5:14:00 AM	3/18/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	18	DF	left fountain outside 115	FD	3/13/2019	8:00:00 PM	3/14/2019	5:17:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	19	DF	right fountain outside 115	FD	3/13/2019	8:00:00 PM	3/14/2019	5:17:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	20	DF	left fountain in boy's locker room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:20:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	21	DF	right fountain in boy's locker room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:20:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	22	DF	left fountain in girl's locker room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:23:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	23	DF	right fountain in girl's locker room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:23:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	24	DF	left fountain outside 108	FD	3/13/2019	8:00:00 PM	3/14/2019	5:27:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	25	DF	right fountain outside 108	FD	3/13/2019	8:00:00 PM	3/14/2019	5:27:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	26	DF	left fountain by stairs 1	FD	3/13/2019	8:00:00 PM	3/14/2019	5:30:00 AM	3/18/2019	<1.0	No

Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	27	DF	right fountain by stairs 1	FD	3/13/2019	8:00:00 PM	3/14/2019	5:30:00 AM	3/18/2019	10.6	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	28	DF	left fountain outside 317	FD	3/13/2019	8:00:00 PM	3/14/2019	5:43:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	29	DF	middle fountain outside 317	FD	3/13/2019	8:00:00 PM	3/14/2019	5:43:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	30	DF	right fountain outside 317	FD	3/13/2019	8:00:00 PM	3/14/2019	5:43:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	31	DF	fountain outside 326	FD	3/13/2019	8:00:00 PM	3/14/2019	5:41:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	32	DF	left fountain outside electrical 4	FD	3/13/2019	8:00:00 PM	3/14/2019	5:39:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	33	DF	right fountain outside electrical 4	FD	3/13/2019	8:00:00 PM	3/14/2019	5:39:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	37	IM	ice machine in kitchen	FD	3/13/2019	8:00:00 PM	3/14/2019	4:50:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	38	KS	2 compartment sink faucets	FD	3/13/2019	8:00:00 PM	3/14/2019	4:50:00 AM	3/18/2019	<1.0	No
Water Testing	Calvert High School	3/30/2019	1	39	KS	left faucet 3 compartment sink	FD	3/13/2019	8:00:00 PM	3/14/2019	4:51:00 AM	3/18/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	40	KS	right faucet 3 compartment sink	FD	3/13/2019	8:00:00 PM	3/14/2019	4:51:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	41	KS	dish sprayer in dish room	FD	3/13/2019	8:00:00 PM	3/14/2019	7:35:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	42	KS	faucet on solo kettle	FD	3/13/2019	8:00:00 PM	3/14/2019	4:52:00 AM	3/18/2019	1.8	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	43	KS	left kettle	FD	3/13/2019	8:00:00 PM	3/14/2019	4:53:00 AM	3/18/2019	1	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	44	KS	right kettle	FD	3/13/2019	8:00:00 PM	3/14/2019	4:53:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	45	IM	ice machine 222	FD	3/13/2019	8:00:00 PM	3/14/2019	4:57:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	46	IM	ice machine in fridge 222	FD	3/13/2019	8:00:00 PM	3/14/2019	4:57:00 AM	3/18/2019	10.1	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	47	CR	teacher faucet	FD	3/13/2019	8:00:00 PM	3/14/2019	4:57:00 AM	3/18/2019	1.1	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	48	CR	far left faucet	FD	3/13/2019	8:00:00 PM	3/14/2019	4:58:00 AM	3/18/2019	<1.0	No

Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	49	CR	left middle faucet	FD	3/13/2019	8:00:00 PM	3/14/2019	4:58:00 AM	3/18/2019	1.8	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	50	CR	middle left faucet	FD	3/13/2019	8:00:00 PM	3/14/2019	4:58:00 AM	3/18/2019	3	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	51	CR	middle right faucet	FD	3/13/2019	8:00:00 PM	3/14/2019	4:59:00 AM	3/18/2019	3.2	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	52	CR	right middle faucet	FD	3/13/2019	8:00:00 PM	3/14/2019	4:59:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	53	CR	far right faucet	FD	3/13/2019	8:00:00 PM	3/14/2019	4:59:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	54	CR	faucet in teachers' lounge 1	FD	3/13/2019	8:00:00 PM	3/14/2019	5:03:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	55	CR	faucet media center office	FD	3/13/2019	8:00:00 PM	3/14/2019	5:03:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	56	CR	faucet in mail room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:10:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	57	NO	faucet in nurse room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:12:00 AM	3/18/2019	<1.0	No
Water Testing	Calvert High School	3/30/2019	1	58	IM	fridge ice machine in nurse room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:12:00 AM	3/18/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	59	CR	front faucet 402	FD	3/13/2019	8:00:00 PM	3/14/2019	5:16:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	60	CR	back faucet 402	FD	3/13/2019	8:00:00 PM	3/14/2019	5:12:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	61	CR	front faucet 404	FD	3/13/2019	8:00:00 PM	3/14/2019	5:18:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	62	CR	back faucet 404	FD	3/13/2019	8:00:00 PM	3/14/2019	5:18:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	63	CR	faucet in 109 office	FD	3/13/2019	8:00:00 PM	3/14/2019	5:20:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	64	CR	faucet in training room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:25:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	65	IM	left ice machine in training room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:25:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	66	IM	right ice machine in training room	FD	3/13/2019	8:00:00 PM	3/14/2019	5:25:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	67	CR	faucet 104	FD	3/13/2019	8:00:00 PM	3/14/2019	5:30:00 AM	3/18/2019	<1.0	No

Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	68	CR	faucet 102	FD	3/13/2019	8:00:00 PM	3/14/2019	5:33:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	69	CR	faucet 100	FD	3/13/2019	8:00:00 PM	3/14/2019	5:33:00 AM	3/18/2019	1.1	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	70	CR	faucet in teacher lounge 2	FD	3/13/2019	8:00:00 PM	3/14/2019	5:41:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	71	CR	faucet in 330	FD	3/13/2019	8:00:00 PM	3/14/2019	5:53:00 AM	3/18/2019	2.1	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	74	CR	faucet 2 compartment sink in stadium concession stand	FD	3/13/2019	8:00:00 PM	3/14/2019	6:04:00 AM	3/18/2019	3.3	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	75	IM	fridge ice machine in teachers lounge	FD	3/13/2019	8:00:00 PM	3/14/2019	5:41:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	76	IM	ice machine in 203	FD	3/13/2019	8:00:00 PM	3/14/2019	5:08:00 AM	3/18/2019	1.1	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	77	CR	faucet in 203	FD	3/13/2019	8:00:00 PM	3/14/2019	5:08:00 AM	3/18/2019	<1.0	No
Water Testing Laboratory of MD	Calvert High School	3/30/2019	1	78	KS	faucet in stage/auditorium concession stand	FD	3/13/2019	8:00:00 PM	3/14/2019	5:22:00 AM	3/18/2019	3.8	No
Water Testing	Calvert High School	2/23/2019	1	34*	DF	Bottle Filler inside the door of the weight room	FD	2/5/2019	4:00:00 PM	2/6/2019	5:41:00 AM	2/14/2019	<1.0	No

Laboratory of MD														
------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Notes: Sample Site 34 was a water fountain that was replaced with a bottle filler in February 2019

2017-2018 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date Water Last Used	Time Water Last Used	Date Sample Collected	Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Calvert High School	7/7/2018	1	34*	DF	fountain inside the door of the weight room	FD	5/30/2018	8:25:00 AM	5/30/2018	4:44:00 PM	5/31/2018	9.5	No
Water Testing Laboratory of MD	Calvert High School	7/7/2018	1	35	DF	fountain by bathroom in weight room	FD	5/30/2018	8:25:00 AM	5/30/2018	4:44:00 PM	5/31/2018	1.6	No
Water Testing Laboratory of MD	Calvert High School	7/7/2018	1	36	DF	fountain in planetarium	FD	5/30/2018	8:25:00 AM	5/30/2018	4:35:00 PM	5/31/2018	1.7	No
Water Testing Laboratory of MD	Calvert High School	7/7/2018	1	72	IM	left ice machine in weight room	FD	5/30/2018	8:25:00 AM	5/30/2018	4:53:00 PM	5/31/2018	<1.0	No
Water Testing Laboratory of MD	Calvert High School	7/7/2018	1	73	IM	right ice machine in weight room	FD	5/30/2018	8:25:00 AM	5/30/2018	4:53:00 PM	5/31/2018	<1.0	No