

Mill Creek Middle School

2018-2019 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date Water Last Used	Time Water Last Used	Date Sample Collected	Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	1	DF	left fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	2	DF	right fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	3	DF	fountain in girls locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	4	DF	fountain in boys locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	5	DF	fountain across 116	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	6	DF	fountain by 101	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	7	DF	fountain by cafeteria	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	8	DF	fountain 212	FD	4/8/2019	8:00:00 PM	4/9/2019	5:54:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	9	DF	fountain 201	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	10	KS	dish room sprayer	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	11	KS	left faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	12	KS	right faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	13	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	14	KS	faucet on prep table	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	15	KS	left kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	1.7	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	16	KS	right kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	1.0	No
Water Testing	Mill Creek Middle School	4/20/2019	1	17	KS	left sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:52:00 AM	4/13/2019	1.6	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	18	KS	right sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.8	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	19	KS	faucet on 2 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	20	CR	faucet in staff lounge	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	21	CR	faucet in 125	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	22	CR	faucet in 127	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	23	HE	front left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	24	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	25	HE	back left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	26	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	27	HE	middle center faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	28	HE	middle right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	29	HE	right middle faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	31	HE	far right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	2.1	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	32	CR	front faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	33	CR	back faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	34	CR	faucet in 109	FD	4/8/2019	8:00:00 PM	4/9/2019	5:45:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	35	DF	fountain by health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	36	NO	faucet in health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:41:00 AM	4/13/2019	<1.0	No
Water Testing	Mill Creek Middle School	4/20/2019	1	37	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	38	CR	faucet 205	FD	4/8/2019	8:00:00 PM	4/9/2019	5:56:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	39	CR	faucet in prep room between 215/217	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.9	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	40	CR	faucet in 103	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	1	DF	left fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	2	DF	right fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	3	DF	fountain in girls locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	4	DF	fountain in boys locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	5	DF	fountain across 116	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	6	DF	fountain by 101	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	7	DF	fountain by cafeteria	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	8	DF	fountain 212	FD	4/8/2019	8:00:00 PM	4/9/2019	5:54:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	9	DF	fountain 201	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	10	KS	dish room sprayer	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	11	KS	left faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	12	KS	right faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	13	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	14	KS	faucet on prep table	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	15	KS	left kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	1.7	No
Water Testing	Mill Creek Middle School	4/20/2019	1	16	KS	right kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	17	KS	left sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:52:00 AM	4/13/2019	1.6	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	18	KS	right sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.8	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	19	KS	faucet on 2 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	20	CR	faucet in staff lounge	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	21	CR	faucet in 125	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	22	CR	faucet in 127	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	23	HE	front left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	24	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	25	HE	back left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	26	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	27	HE	middle center faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	28	HE	middle right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	29	HE	right middle faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	31	HE	far right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	2.1	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	32	CR	front faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	33	CR	back faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	34	CR	faucet in 109	FD	4/8/2019	8:00:00 PM	4/9/2019	5:45:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	35	DF	fountain by health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No
Water Testing	Mill Creek Middle School	4/20/2019	1	36	NO	faucet in health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:41:00 AM	4/13/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	37	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	38	CR	faucet 205	FD	4/8/2019	8:00:00 PM	4/9/2019	5:56:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	39	CR	faucet in prep room between 215/217	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.9	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	40	CR	faucet in 103	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	1	DF	left fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	2	DF	right fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	3	DF	fountain in girls locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	4	DF	fountain in boys locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	5	DF	fountain across 116	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	6	DF	fountain by 101	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	7	DF	fountain by cafeteria	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	8	DF	fountain 212	FD	4/8/2019	8:00:00 PM	4/9/2019	5:54:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	9	DF	fountain 201	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	10	KS	dish room sprayer	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	11	KS	left faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	12	KS	right faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	13	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	14	KS	faucet on prep table	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing	Mill Creek Middle School	4/20/2019	1	15	KS	left kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	1.7	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	16	KS	right kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	17	KS	left sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:52:00 AM	4/13/2019	1.6	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	18	KS	right sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.8	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	19	KS	faucet on 2 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	20	CR	faucet in staff lounge	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	21	CR	faucet in 125	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	22	CR	faucet in 127	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	23	HE	front left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	24	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	25	HE	back left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	26	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	27	HE	middle center faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	28	HE	middle right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	29	HE	right middle faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	31	HE	far right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	2.1	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	32	CR	front faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	33	CR	back faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	34	CR	faucet in 109	FD	4/8/2019	8:00:00 PM	4/9/2019	5:45:00 AM	4/13/2019	<1.0	No
Water Testing	Mill Creek Middle School	4/20/2019	1	35	DF	fountain by health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	36	NO	faucet in health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:41:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	37	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	38	CR	faucet 205	FD	4/8/2019	8:00:00 PM	4/9/2019	5:56:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	39	CR	faucet in prep room between 215/217	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.9	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	40	CR	faucet in 103	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	1	DF	left fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	2	DF	right fountain by gym	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	3	DF	fountain in girls locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	4	DF	fountain in boys locker room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:59:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	5	DF	fountain across 116	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	6	DF	fountain by 101	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	7	DF	fountain by cafeteria	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	8	DF	fountain 212	FD	4/8/2019	8:00:00 PM	4/9/2019	5:54:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	9	DF	fountain 201	FD	4/8/2019	8:00:00 PM	4/9/2019	5:57:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	10	KS	dish room sprayer	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	11	KS	left faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	12	KS	right faucet 3 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:47:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	13	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing	Mill Creek Middle School	4/20/2019	1	14	KS	faucet on prep table	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	15	KS	left kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	1.7	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	16	KS	right kettle	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	17	KS	left sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:52:00 AM	4/13/2019	1.6	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	18	KS	right sprayer by walk-in	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.8	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	19	KS	faucet on 2 compartment sink	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	20	CR	faucet in staff lounge	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	21	CR	faucet in 125	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	22	CR	faucet in 127	FD	4/8/2019	8:00:00 PM	4/9/2019	5:43:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	23	HE	front left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No

Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	24	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:48:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	25	HE	back left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	26	HE	middle left faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:49:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	27	HE	middle center faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	28	HE	middle right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:50:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	29	HE	right middle faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	31	HE	far right faucet 120	FD	4/8/2019	8:00:00 PM	4/9/2019	5:51:00 AM	4/13/2019	2.1	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	32	CR	front faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	33	CR	back faucet 111	FD	4/8/2019	8:00:00 PM	4/9/2019	5:46:00 AM	4/13/2019	<1.0	No
Water Testing	Mill Creek Middle School	4/20/2019	1	34	CR	faucet in 109	FD	4/8/2019	8:00:00 PM	4/9/2019	5:45:00 AM	4/13/2019	<1.0	No

Laboratory of MD														
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	35	DF	fountain by health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:42:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	36	NO	faucet in health room	FD	4/8/2019	8:00:00 PM	4/9/2019	5:41:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	37	IM	ice machine	FD	4/8/2019	8:00:00 PM	4/9/2019	5:40:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	38	CR	faucet 205	FD	4/8/2019	8:00:00 PM	4/9/2019	5:56:00 AM	4/13/2019	<1.0	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	2	39	CR	faucet in prep room between 215/217	FD	4/8/2019	8:00:00 PM	4/9/2019	5:53:00 AM	4/13/2019	1.9	No
Water Testing Laboratory of MD	Mill Creek Middle School	4/20/2019	1	40	CR	faucet in 103	FD	4/8/2019	8:00:00 PM	4/9/2019	5:44:00 AM	4/13/2019	<1.0	No