

Southern Middle School

2018-2019 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date and Time Water Last Used	Date and Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Southern Middle School	6/25/2019	1	57	DF	Fountain in Boy's Locker Room	FD	6/5/19 5:30PM	6/6/19 6:06AM	6/8/2019	0.00	No
Water Testing Laboratory of MD	Southern Middle School	6/25/2019	1	58	DF	Fountain in Girl's Locker Room	FD	6/5/19 5:30PM	6/6/19 6:07AM	6/8/2019	1.90	No

2017-2018 Testing Results

Laboratory Name	School Name	Laboratory Reporting Date	Floor #	School Outlet ID/Floor Plan ID	Sample Tap/Outlet Type (code)	Sample Tap/Outlet Description/Location	Sample Type (Code)	Date and Time Water Last Used	Date and Time Sample Collected	Analysis Date	Lead Sample Result (ppb)	≥ 20.5 ppb AL?
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	1	DF	left fountain by safety advocate room	FD	5/02/18 6:15PM	5/03/18 05:36 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	2	DF	right fountain by safety advocate room	FD	5/02/18 6:15PM	5/03/18 05:36 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	3	DF	left fountain across from 8	FD	5/02/18 6:15PM	5/03/18 05:47 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	4	DF	right fountain across from 8	FD	5/02/18 6:15PM	5/03/18 05:47 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	5	DF	fountain across from 17	FD	5/02/18 6:15PM	5/03/18 05:52 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	6	DF	fountain between 18 & 23	FD	5/02/18 6:15PM	5/03/18 05:46 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	7	DF	fountain between 19 & 22	FD	5/02/18 6:15PM	5/03/18 05:48 AM	5/8/2018	<1.0	No

Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	8	DF	left fountain across from 28	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	9	DF	right fountain across from 28	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	10	DF	fountain outside of 32	FD	5/02/18 6:15PM	5/03/18 06:01 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	11	DF	left fountain in cafeteria	FD	5/02/18 6:15PM	5/03/18 05:31 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	12	DF	right fountain in cafeteria	FD	5/02/18 6:15PM	5/03/18 05:31 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	13	DF	left fountain outside of 41	FD	5/02/18 6:15PM	5/03/18 06:03 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	14	NO	right fountain outside of 41	FD	5/02/18 6:15PM	5/03/18 06:03 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	15	TL	faucet in nurse room	FD	5/02/18 6:15PM	5/03/18 05:33 AM	5/8/2018	1.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	16	CR	faucet in main office	FD	5/02/18 6:15PM	5/03/18 05:35 AM	5/8/2018	4.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	17	CR	faucet in 2	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	8.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	18	CR	faucet in 3	FD	5/02/18 6:15PM	5/03/18 05:39 AM	5/8/2018	12.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	19	CR	faucet in 4	FD	5/02/18 6:15PM	5/03/18 05:40 AM	5/8/2018	11.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	20	CR	faucet in 5	FD	5/02/18 6:15PM	5/03/18 05:40 AM	5/8/2018	2.2	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	21	CR	faucet in 6	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	14.6	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	22	CR	faucet in 7	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	6.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	23	CR	faucet in 8	FD	5/02/18 6:15PM	5/03/18 05:45 AM	5/8/2018	8.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	24	CR	faucet in 9	FD	5/02/18 6:15PM	5/03/18 05:48 AM	5/8/2018	12.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	25	CR	faucet in 10	FD	5/02/18 6:15PM	5/03/18 05:49 AM	5/8/2018	3.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	26	CR	faucet in 11	FD	5/02/18 6:15PM	5/03/18 05:51 AM	5/8/2018	5.6	No

Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	27	CR	faucet in 12	FD	5/02/18 6:15PM	5/03/18 05:51 AM	5/8/2018	9.2	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	28	CR	faucet in 15	FD	5/02/18 6:15PM	5/03/18 05:53 AM	5/8/2018	8.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	29	CR	faucet in 19	FD	5/02/18 6:15PM	5/03/18 05:49 AM	5/8/2018	5.1	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	30	CR	faucet in 23	FD	5/02/18 6:15PM	5/03/18 05:54 AM	5/8/2018	7.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	31	CR	closest faucet in 23	FD	5/02/18 6:15PM	5/03/18 05:39 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	32	CR	farthest faucet in 26	FD	5/02/18 6:15PM	5/03/18 05:39 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	33	CR	left faucet in 27	FD	5/02/18 6:15PM	5/03/18 05:45 AM	5/8/2018	11.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	34	CR	right faucet in 27	FD	5/02/18 6:15PM	5/03/18 05:45 AM	5/8/2018	8.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	35	CR	faucet in 30	FD	5/02/18 6:15PM	5/03/18 05:43 AM	5/8/2018	7.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	36	CR	faucet in 31	FD	5/02/18 6:15PM	5/03/18 05:43 AM	5/8/2018	2.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	37	CR	faucet in 29	FD	5/02/18 6:15PM	5/03/18 05:40 AM	5/8/2018	10.9	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	38	CR	faucet in 32	FD	5/02/18 6:15PM	5/03/18 05:38 AM	5/8/2018	13.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	39	HE	First right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	2.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	40	HE	middle right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	2.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	41	HE	back right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	2.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	42	HE	middle right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	3.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	43	HE	middle-middle faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	1.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	44	HE	left middle faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	1.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	45	DF	water fountain in 36	FD	5/02/18 6:15PM	5/03/18 05:33 AM	5/8/2018	<1.0	No

Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	46	CR	Faucet in 39	FD	5/02/18 6:15PM	5/03/18 06:01 AM	5/8/2018	7.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	47	CR	faucet in testing room in media center	FD	5/02/18 6:15PM	5/03/18 05:51 AM	5/8/2018	3.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	48	CR	faucet in 40	FD	5/02/18 6:15PM	5/03/18 05:55 AM	5/8/2018	3.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	49	TL	faucet in lounge	FD	5/02/18 6:15PM	5/03/18 06:04 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	50	KS	single faucet two compartment sink in kitchen	FD	5/02/18 6:15PM	5/03/18 05:28 AM	5/8/2018	1.1	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	51	KS	left faucet two compartment sink in kitchen	FD	5/02/18 6:15PM	5/03/18 05:29 AM	5/8/2018	1.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	52	KS	right faucet two compartment sink in kitchen	FD	5/02/18 6:15PM	5/03/18 05:29 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	53	KS	single faucet on prep table in kitchen	FD	5/02/18 6:15PM	5/03/18 05:27 AM	5/8/2018	1.1	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	54	CR	Left faucet in 32	FD	5/02/18 6:15PM	5/03/18 05:27 AM	5/8/2018	6.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	55	IM	Ice machine in building service room	FD	5/02/18 6:15PM	5/03/18 05:30 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	56	IM	Ice machine in kitcehn	FD	5/02/18 6:15PM	5/03/18 05:27 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	1	DF	left fountain by safety advocate room	FD	5/02/18 6:15PM	5/03/18 05:36 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	2	DF	right fountain by safety advocate room	FD	5/02/18 6:15PM	5/03/18 05:36 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	3	DF	left fountain accros from 8	FD	5/02/18 6:15PM	5/03/18 05:47 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	4	DF	right fountain across from 8	FD	5/02/18 6:15PM	5/03/18 05:47 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	5	DF	fountain across from 17	FD	5/02/18 6:15PM	5/03/18 05:52 AM	5/7/2018	<1.0	No

Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	6	DF	fountain between 18 & 23	FD	5/02/18 6:15PM	5/03/18 05:46 AM	5/7/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	7	DF	fountain between 19 & 22	FD	5/02/18 6:15PM	5/03/18 05:48 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	8	DF	left fountain across from 28	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	9	DF	right fountain across from 28	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	10	DF	fountain outside of 32	FD	5/02/18 6:15PM	5/03/18 06:01 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	11	DF	left fountain in cafeteria	FD	5/02/18 6:15PM	5/03/18 05:31 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	12	DF	right fountain in cafeteria	FD	5/02/18 6:15PM	5/03/18 05:31 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	13	DF	left fountain outside of 41	FD	5/02/18 6:15PM	5/03/18 06:03 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	14	NO	right fountain outside of 41	FD	5/02/18 6:15PM	5/03/18 06:03 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	15	TL	faucet in nurse room	FD	5/02/18 6:15PM	5/03/18 05:33 AM	5/8/2018	1.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	16	CR	faucet in main office	FD	5/02/18 6:15PM	5/03/18 05:35 AM	5/8/2018	4.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	17	CR	faucet in 2	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	8.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	18	CR	faucet in 3	FD	5/02/18 6:15PM	5/03/18 05:39 AM	5/8/2018	12.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	19	CR	faucet in 4	FD	5/02/18 6:15PM	5/03/18 05:40 AM	5/8/2018	11.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	20	CR	faucet in 5	FD	5/02/18 6:15PM	5/03/18 05:40 AM	5/8/2018	2.2	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	21	CR	faucet in 6	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	14.6	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	22	CR	faucet in 7	FD	5/02/18 6:15PM	5/03/18 05:41 AM	5/8/2018	6.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	23	CR	faucet in 8	FD	5/02/18 6:15PM	5/03/18 05:45 AM	5/8/2018	8.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	24	CR	faucet in 9	FD	5/02/18 6:15PM	5/03/18 05:48 AM	5/8/2018	12.7	No

Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	25	CR	faucet in 10	FD	5/02/18 6:15PM	5/03/18 05:49 AM	5/8/2018	3.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	26	CR	faucet in 11	FD	5/02/18 6:15PM	5/03/18 05:51 AM	5/8/2018	5.6	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	27	CR	faucet in 12	FD	5/02/18 6:15PM	5/03/18 05:51 AM	5/8/2018	9.2	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	28	CR	faucet in 15	FD	5/02/18 6:15PM	5/03/18 05:53 AM	5/8/2018	8.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	29	CR	faucet in 19	FD	5/02/18 6:15PM	5/03/18 05:49 AM	5/8/2018	5.1	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	30	CR	faucet in 23	FD	5/02/18 6:15PM	5/03/18 05:54 AM	5/8/2018	7.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	31	CR	closest faucet in 23	FD	5/02/18 6:15PM	5/03/18 05:39 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	32	CR	farthest faucet in 26	FD	5/02/18 6:15PM	5/03/18 05:39 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	33	CR	left faucet in 27	FD	5/02/18 6:15PM	5/03/18 05:45 AM	5/8/2018	11.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	34	CR	right faucet in 27	FD	5/02/18 6:15PM	5/03/18 05:45 AM	5/8/2018	8.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	35	CR	faucet in 30	FD	5/02/18 6:15PM	5/03/18 05:43 AM	5/8/2018	7.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	36	CR	faucet in 31	FD	5/02/18 6:15PM	5/03/18 05:43 AM	5/8/2018	2.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	37	CR	faucet in 29	FD	5/02/18 6:15PM	5/03/18 05:40 AM	5/8/2018	10.9	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	38	CR	faucet in 32	FD	5/02/18 6:15PM	5/03/18 05:38 AM	5/8/2018	13.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	39	HE	First right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	2.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	40	HE	middle right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	2.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	41	HE	back right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	2.5	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	42	HE	middle right faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	3.4	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	43	HE	middle-middle faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	1.8	No

Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	44	HE	left middle faucet in 33	FD	5/02/18 6:15PM	5/03/18 05:37 AM	5/8/2018	1.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	45	DF	water fountain in 36	FD	5/02/18 6:15PM	5/03/18 05:33 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	46	CR	Faucet in 39	FD	5/02/18 6:15PM	5/03/18 06:01 AM	5/8/2018	7.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	47	CR	faucet in testing room in media center	FD	5/02/18 6:15PM	5/03/18 05:51 AM	5/8/2018	3.8	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	48	CR	faucet in 40	FD	5/02/18 6:15PM	5/03/18 05:55 AM	5/8/2018	3.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	49	TL	faucet in lounge	FD	5/02/18 6:15PM	5/03/18 06:04 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	50	KS	single faucet two compartment sink in kitchen	FD	5/02/18 6:15PM	5/03/18 05:28 AM	5/8/2018	1.1	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	51	KS	left faucet two compartment sink in kitchen	FD	5/02/18 6:15PM	5/03/18 05:29 AM	5/8/2018	1.3	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	52	KS	right faucet two compartment sink in kitchen	FD	5/02/18 6:15PM	5/03/18 05:29 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	53	KS	single faucet on prep table in kitchen	FD	5/02/18 6:15PM	5/03/18 05:27 AM	5/8/2018	1.1	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	54	CR	Left faucet in 32	FD	5/02/18 6:15PM	5/03/18 05:27 AM	5/8/2018	6.7	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	55	IM	Ice machine in building service room	FD	5/02/18 6:15PM	5/03/18 05:30 AM	5/8/2018	<1.0	No
Water Testing Laboratory of MD	Southern Middle School	6/16/2018	1	56	IM	Ice machine in kitcehn	FD	5/02/18 6:15PM	5/03/18 05:27 AM	5/8/2018	<1.0	No